

## Declaration of Operational Compliance (DOC)

of an amusement device in accordance with Section D of HSG 175:  
Fairgrounds and amusement parks - Guidance on safe practice



<b>Controller:</b>	Chris Winters	<b>DOC No:</b>	W00339
<b>Member No.:</b>		<b>Expiry Date:</b>	31/01/2023
<b>Address:</b>	261 Oldbury Road, Rowley, Regis, West Midlands	<b>Valid From:</b>	11/02/2022
<b>Post Code:</b>	B65 0PP	<b>Issue Date:</b>	11/02/2022
<b>ADIPS ID No:</b>	14026	<b>Manufacturer:</b>	Euro Jumper
<b>Device Name:</b>	Mobile 4 in 1 bungee Trampoline	<b>Manufacturer Serial No:</b>	1022
<b>Description:</b>	Mobile 4 in 1 bungee Trampoline	<b>Year of Manufacture:</b>	
		<b>Year of Importation:</b>	2015
		<b>Assn. Machine Serial No.:</b>	

### Pre-Use Inspection Reports

Inspection Type	Name of Inspection Body	Report Ref. No
Design Review	Tony Mogford Associates Ltd	CW.BT1022.DR
Assessment of Conformity to Design	Tony Mogford Associates Ltd	CW.BT1022.AC
Initial Test	Tony Mogford Associates Ltd	CW.BT1022.IT

### In-Service Annual Inspection Reports

Inspection Type	Name of Inspection Body	Report Ref. No	Expiry Date
Mechanical/Structural Integrity	TK Inspections	3909-01	31/01/2023
Functional Test	TK Inspections	3909-01	31/01/2023
NDT	TK Inspections	3909-01	31/01/2023
Electrical Safety	TK Inspections	3909-01	31/01/2023

### About this document

This document is a receipt style certificate confirming that an inspection of amusement device ADIPS ID No. 14026 has been recorded in the ADIPS database. This document has been issued electronically by the Registered Inspection Body TK Inspections Hull Ltd, Registration No. 191522, who has confirmed that:

- They have been notified of all information known to Chris Winters, regarding modifications, repairs and safety issues or incidents, that have occurred since the issue of any previous DOC and that may be relevant to the safety of the device.
- Subject to and relying upon the contents of the examination reports listed above, the safety critical aspects of the device, at the time of inspection, have not deteriorated to an extent liable to cause danger, provided that the device is maintained and operated in a safe and proper manner.
- The Industry required documents relating to any safety critical modifications (that they have been notified of) have been documented in the Operations Manual.
- The pre-use inspections (Design Review, Assessment of Conformity to Design and Initial Test) have been carried out and are documented in the operations manual.
- The device has been upgraded where necessary to minimise danger as advised by Industry Technical Bulletins or HSE guidance specifically relating to this device.
- This document may be verified at [www.adipsdoc.co.uk](http://www.adipsdoc.co.uk) or contact ADIPS on 0191.5166381.

This DOC is issued by and on behalf of:

TK Inspections Hull Ltd  
1 Parthian Road  
Hull  
HU9 4SU  
Tel:  
Registration No. 191522

Scan the QR code to check that this certificate is genuine

